Main Street Area Survey (Sheridan Livery Stable) 29-33 North Main Street Lexington (independent city) Virginia

74 82-LEX

## **PHOTOGRAPH**

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, D.C. 20240

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS VA 82-LEX, 12-

## ARCHITECTURAL DATA FORM

HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)  Sheridan Livery Stable (recorded as part of the Main Street Area Survey)  VA-897-D  SECONDARY OR COMMON NAMES OF STRUCTURE  COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)  29-33 North Main Street  DATE OF CONSTRUCTION (INCLUDE SOURCE)  1887  SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)  Integral part of Lexington's historic Main Street. Until 1919, was livery stable of prominant businessama John Sheridan. From 1919 to 1970 served as the Kockbridge Laundry.  STYLE (IF APPROPRIATE)  MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)  3rick  HAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)  Rectangular; 2 stories (plus basement on sloping rear of the building); steep shed roof; about 10 plus page of the building); steep shed roof; about 10 plus plus plus plus plus plus plus plus	STATE	COUNTY		TOWN OR VICINITY		
Sheridan Livery Stable (recorded as part of the Main Street Area Survey)  SECONDARY OR COMMON NAMES OF STRUCTURE  COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 29–33 North Main Street  DATE OF CONSTRUCTION (INCLUDE SOURCE)  1887  SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)  Integral part of Lexington's historic Main Street. Until 1919, was livery stable of prominant businessman John Sheridan. From 1919 to 1970 served as the Rockbridge Laundry.  STYLE (IF APPROPRIATE)  MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)  Brick  HAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)  Rectangular; 2 stories (plus basement on sloping rear of the building); steep shed roof; a-bay front; 9-bay side (including addition to rear).  EXTERIOR FEATURES OF NOTE  Large arched openings which originally accommodated carriage doors; brick plasters divide the main and side facades into distinct bays; simple bracketed cornice  INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)  MAJOR ALTERATIONS AND ADDITIONS WITH DATES  After 1919, an addition was made to the east and the basement was excavated. Also the arched openings of the main facade were filled in. In 1973 the building was bought and rehabilitated.  PRESENT CONDITION AND USE  As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)  Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.	Virginia			Lexington (independent city)		
SECONDARY OR COMMON NAMES OF STRUCTURE  COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)  29—33 North Main Street  DATE OF CONSTRUCTION (INCLUDE SOURCE)  1887  SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)  Integral part of Lexington's historic Main Street. Until 1919, was livery stable of prominant businessman John Sheridan. From 1919 to 1970 served as the Rockbridge Laundry.  STYLE (IF APPROPRIATE)  MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)  Brick  HAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)  Rectangular; 2 stories (plus basement on sloping rear of the building); steep shed roof; 4-bay front; 9-bay side (including addition to rear)  EXTERIOR FEATURES OF NOTE  Large arched openings which originally accomodated carriage doors; brick pilasters divide the main and side facades into distinct bays; simple bracketed cornice  INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)  MAJOR ALTERATIONS AND ADDITIONS WITH DATES  After 1919, an addition was made to the east and the basement was excavated. Also the arched openings of the main facade were filled in. In 1973 the building was bought and rehabilitated.  PRESENT CONDITION AND USE  As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION SINCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)  Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.	HISTORIC NAME OF STRUCTURE (INCL	UDE SOURCE FOR	NAME)	<u> </u>	HABS NO.	
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)  29-33 North Main Street  DATE OF CONSTRUCTION (INCLUDE SOURCE)  1887  SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) Integral part of Lexington's historic Main Street. Until 1919, was livery stable of prominant businessman John Sheridan. From 1919 to 1970 served as the Rockbridge Laundry.  STYLE (IF APPROPRIATE)  MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)  Brick  HAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) Rectangular; 2 stories (plus basement on sloping rear of the building); steep shed roof; a-hay front; 9-hay side (including addition to rear)  EXTENIOR FEATURES OF NOTE Large arched openings which originally accomodated carriage doors; brick pilasters divide the main and side facades into distinct bays; simple bracketed cornice  INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)  MAJOR ALTERATIONS AND ADDITIONS WITH DATES After 1919, an addition was made to the east and the basement was excavated. Also the arched openings of the main facade were filled in. In 1973 the building was bought and rehabilitated.  PRESENT CONDITION AND USE As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)  Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Ristoric Lexington. 1977.	Sheridan Livery Stable (recorded as part of the Main Street Area Survey) VA-897-D					
DATE OF CONSTRUCTION (INCLUDE SOURCE)  1887  SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) Integral part of Lexington's historic Main Street. Until 1919, was livery stable of prominant businessman John Sheridan. From 1919 to 1970 served as the Rockbridge Laundry.  STYLE (IF APPROPRIATE)  MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)  Brick  HAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) Rectangular; 2 stories (plus basement on sloping rear of the building); steep shed roof;  4-bay front: 9-bay stide (Including addition to rear)  EXTERIOR FEATURES OF NOTE Large arched openings which originally accommodated carriage doors; brick pilasters divide the main and side facades into distinct bays; simple bracketed cornice  INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)  MAJOR ALTERATIONS AND ADDITIONS WITH DATES After 1919, an addition was made to the east and the basement was excavated. Also the arched openings of the main facade were filled in. In 1973 the building was bought and rehabilitated.  PRESENT CONDITION AND USE As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)  Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.	SECONDARY OR COMMON NAMES OF STRUCTURE					
DATE OF CONSTRUCTION (INCLUDE SOURCE)  1887  SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) Integral part of Lexington's historic Main Street. Until 1919, was livery stable of prominant businessman John Sheridan. From 1919 to 1970 served as the Rockbridge Laundry.  STYLE (IF APPROPRIATE)  MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)  Brick  HAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) Rectangular; 2 stories (plus basement on sloping rear of the building); steep shed roof;  4-bay front: 9-bay stda (Including addition to rear)  EXTERIOR FEATURES OF NOTE Large arched openings which originally accommodated carriage doors; brick pilasters divide the main and side facades into distinct bays; simple bracketed cornice  INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)  MAJOR ALTERATIONS AND ADDITIONS WITH DATES After 1919, an addition was made to the east and the basement was excavated. Also the arched openings of the main facade were filled in. In 1973 the building was bought and rehabilitated.  PRESENT CONDITION AND USE As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)  Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.						
DATE OF CONSTRUCTION (INCLUDE SOURCE)  1887  SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) Integral part of Lexington's historic Main Street. Until 1919, was livery stable of prominent businessman John Sheridan. From 1919 to 1970 served as the Rockbridge Laundry.  STYLE (IF APPROPRIATE)  MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Brick  HAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) Rectangular; 2 stories (plus basement on sloping rear of the building); steep shed roof; 4-bay front; 9-bay side (including addition to rear) EXTERIOR FEATURES OF NOTE Large arched openings which originally accommodated carriage doors; brick pilasters divide the main and side facades into distinct bays; simple bracketed cornice  INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)  MAJOR ALTERATIONS AND ADDITIONS WITH DATES After 1919, an addition was made to the east and the basement was excavated. Also the arched openings of the main facade were filled in. In 1973 the building was bought and rehabilitated.  PRESENT CONDITION AND USE As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.	COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)					
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)  Integral part of Lexington's historic Main Street. Until 1919, was livery stable of prominant businessman John Sheridan. From 1919 to 1970 served as the Rockbridge Laundry.  SIYLE (IF APPROPRIATE)  MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)  Brick  HAPEAND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)  Rectangular; 2 stories (plus basement on sloping rear of the building); steep shed roof; a-bay front; 9-bay side (including addition to rear)  EXTERIOR FEATURES OF NOTE  Large arched openings which originally accommodated carriage doors; brick pilasters divide the main and side facades into distinct bays; simple bracketed cornice  INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)  MAJOR ALTERATIONS AND ADDITIONS WITH DATES  After 1919, an addition was made to the east and the basement was excavated. Also the arched openings of the main facade were filled in. In 1973 the building was bought and rehabilitated.  PRESENT CONDITION AND USE  As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION AS APPROPRIATE  COMPILER, AFFILIATION  DATE	29-33 North Main Street					
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)  Integral part of Lexington's historic Main Street. Until 1919, was livery stable of prominant businessman John Sheridan. From 1919 to 1970 served as the Rockbridge Laundry.  STYLE (IF APPROPRIATE)  MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)  Brick  HAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)  Rectangular; 2 stories (plus basement on sloping rear of the building); steep shed roof; 4-bay front; 9-bay side (including addition to rear)  EXTERIOR FEATURES OF NOTE  Large arched openings which originally accommodated carriage doors; brick pilasters divide the main and side facades into distinct bays; simple bracketed cornice  INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)  MAJOR ALTERATIONS AND ADDITIONS WITH DATES  After 1919, an addition was made to the east and the basement was excavated. Also the arched openings of the main facade were filled in. In 1973 the building was bought and rehabilitated.  PRESENT CONDITION AND USE  As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)  Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.	DATE OF CONSTRUCTION (INCLUDE SOURCE)  ARCHITECT(S) (I		ARCHITECT(S) (INC.	CLUDE SOURCE)		
Integral part of Lexington's historic Main Street. Until 1919, was livery stable of prominant businessman John Sheridan. From 1919 to 1970 served as the Rockbridge Laundry.  STYLE (IFAPPROPRIATE)  MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)  Brick  HAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)  Rectangular; 2 stories (plus basement on sloping rear of the building); steep shed roof; 4-bay front; 9-bay side (including addition to rear)  EXTERIOR FEATURES OF NOTE  Large arched openings which originally accommodated carriage doors; brick pilasters divide the main and side facades into distinct bays; simple bracketed cornice  INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)  MAJOR ALTERATIONS AND ADDITIONS WITH DATES  After 1919, an addition was made to the east and the basement was excavated. Also the arched openings of the main facade were filled in. In 1973 the building was bought and rehabilitated.  PRESENT CONDITION AND USE  As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)  Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.	1887					
Prominant businessman John Sheridan. From 1919 to 1970 served as the Rockbridge Laundry.  STYLE (IF APPROPRIATE)  MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)  Brick  HAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)  Rectangular; 2 stories (plus basement on sloping rear of the building); steep shed roof;  \$\frac{4-\text{bay}}{4-\text{bay}} \text{ front: 9-\text{bay}} \text{ side (including addition to rear)}  EXTERIOR FEATURES OF NOTE  Large arched openings which originally accommodated carriage doors; brick pilasters divide the main and side facades into distinct bays; simple bracketed cornice  INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)  MAJOR ALTERATIONS AND ADDITIONS WITH DATES  After 1919, an addition was made to the east and the basement was excavated. Also the arched openings of the main facade were filled in. In 1973 the building was bought and rehabilitated.  PRESENT CONDITION AND USE  As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)  Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.	SIGN IFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUOE ORIGINAL USE OF STRUCTURE)					
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)  Brick  HAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)  Rectangular; 2 stories (plus basement on sloping rear of the building); steep shed roof;  4-bay front; 9-bay side (including addition to rear)  EXTERIOR FEATURES OF NOTE  Large arched openings which originally accomodated carriage doors; brick pilasters divide the main and side facades into distinct bays; simple bracketed cornice  INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)  MAJOR ALTERATIONS AND ADDITIONS WITH DATES  After 1919, an addition was made to the east and the basement was excavated. Also the arched openings of the main facade were filled in. In 1973 the building was bought and rehabilitated.  PRESENT CONDITION AND USE  As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)  Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.						
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Brick  HAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) Rectangular; 2 stories (plus basement on sloping rear of the building); steep shed roof;  \$\frac{4-\text{bay}}{4-\text{bay}} \text{front; 9-\text{bay}} \text{side} \text{(including addition to rear).}  EXTERIOR FEATURES OF NOTE Large arched openings which originally accommodated carriage doors; brick pilasters divide the main and side facades into distinct bays; simple bracketed cornice  INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)  MAJOR ALTERATIONS AND ADDITIONS WITH DATES After 1919, an addition was made to the east and the basement was excavated. Also the arched openings of the main facade were filled in. In 1973 the building was bought and rehabilitated.  PRESENT CONDITION AND USE As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION //NCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.	prominant businessman John Sheridan. From 1919 to 1970 Served as the Rockbridge Laundry.					
HAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) Rectangular; 2 stories (plus basement on sloping rear of the building); steep shed roof; 4-bay front; 9-bay side (Including addition to rear) EXTERIOR FEATURES OF NOTE Large arched openings which originally accomodated carriage doors; brick pilasters divide the main and side facades into distinct bays; simple bracketed cornice  INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)  MAJOR ALTERATIONS AND ADDITIONS WITH DATES After 1919, an addition was made to the east and the basement was excavated. Also the arched openings of the main facade were filled in. In 1973 the building was bought and rehabilitated.  PRESENT CONDITION AND USE As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.	STYLE (IF APPROPRIATE)					
HAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) Rectangular; 2 stories (plus basement on sloping rear of the building); steep shed roof; 4-bay front; 9-bay side (including addition to rear) EXTERIOR FEATURES OF NOTE Large arched openings which originally accomodated carriage doors; brick pilasters divide the main and side facades into distinct bays; simple bracketed cornice  INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)  MAJOR ALTERATIONS AND ADDITIONS WITH DATES After 1919, an addition was made to the east and the basement was excavated. Also the arched openings of the main facade were filled in. In 1973 the building was bought and rehabilitated.  PRESENT CONDITION AND USE As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.	MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)					
Rectangular; 2 stories (plus basement on sloping rear of the building); steep shed roof;  4-bay front; 9-bay side (including addition to rear).  EXTERIOR FEATURES OF NOTE  Large arched openings which originally accomodated carriage doors; brick pilasters divide the main and side facades into distinct bays; simple bracketed cornice  INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)  MAJOR ALTERATIONS AND ADDITIONS WITH DATES  After 1919, an addition was made to the east and the basement was excavated. Also the arched openings of the main facade were filled in. In 1973 the building was bought and rehabilitated.  PRESENT CONDITION AND USE  As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)  Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.	Brick					
4-bay front: 9-hay side (including addition to rear)  EXTERIOR FEATURES OF NOTE Large arched openings which originally accomodated carriage doors; brick pilasters divide the main and side facades into distinct bays; simple bracketed cornice  INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)  MAJOR ALTERATIONS AND ADDITIONS WITH DATES After 1919, an addition was made to the east and the basement was excavated. Also the arched openings of the main facade were filled in. In 1973 the building was bought and rehabilitated.  PRESENT CONDITION AND USE As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.  COMPILER, AFFILIATION  DATE						
EXTERIOR FEATURES OF NOTE Large arched openings which originally accomodated carriage doors; brick pilasters divide the main and side facades into distinct bays; simple bracketed cornice  INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)  MAJOR ALTERATIONS AND ADDITIONS WITH DATES After 1919, an addition was made to the east and the basement was excavated. Also the arched openings of the main facade were filled in. In 1973 the building was bought and rehabilitated.  PRESENT CONDITION AND USE As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.  COMPILER, AFFILIATION  DATE						
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)  MAJOR ALTERATIONS AND ADDITIONS WITH DATES  After 1919, an addition was made to the east and the basement was excavated. Also the arched openings of the main facade were filled in. In 1973 the building was bought and rehabilitated.  PRESENT CONDITION AND USE  As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)  Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.  COMPILER, AFFILIATION  DATE	EXTERIOR FEATURES OF NOTE Large arched openings which originally accomodated carriage doors; brick pilasters divide					
MAJOR ALTERATIONS AND ADDITIONS WITH DATES  After 1919, an addition was made to the east and the basement was excavated. Also the arched openings of the main facade were filled in. In 1973 the building was bought and rehabilitated.  PRESENT CONDITION AND USE  As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)  Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.  COMPILER, AFFILIATION  DATE	the main and side facades into distinct bays; simple bracketed cornice					
MAJOR ALTERATIONS AND ADDITIONS WITH DATES  After 1919, an addition was made to the east and the basement was excavated. Also the arched openings of the main facade were filled in. In 1973 the building was bought and rehabilitated.  PRESENT CONDITION AND USE  As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)  Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.  COMPILER, AFFILIATION  DATE	INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR DI ANS 15 NOT SKETCHEO)					
After 1919, an addition was made to the east and the basement was excavated. Also the arched openings of the main facade were filled in. In 1973 the building was bought and rehabilitated.  PRESENT CONDITION AND USE As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.  COMPILER, AFFILIATION  DATE	THE CHOIL ENGINEER LOOK LAND, I NOT SKETCHED!					
After 1919, an addition was made to the east and the basement was excavated. Also the arched openings of the main facade were filled in. In 1973 the building was bought and rehabilitated.  PRESENT CONDITION AND USE As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.  COMPILER, AFFILIATION  DATE						
After 1919, an addition was made to the east and the basement was excavated. Also the arched openings of the main facade were filled in. In 1973 the building was bought and rehabilitated.  PRESENT CONDITION AND USE As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.  COMPILER, AFFILIATION  DATE	MAJOR ALTERATIONS AND ADDITION	SWITH DATES		<del> </del>		
PRESENT CONDITION AND USE As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.  COMPILER, AFFILIATION  DATE	ł		st and the baseme	ent was exc	avated. Also the	
PRESENT CONDITION AND USE As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)  Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.  COMPILER, AFFILIATION  DATE		facade were fi	lled in. I <b>in</b> 1973	3 the build	ing was bought and	
As of 1977, the building was being used to house specialty shops and a small theatre.  OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)  Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.  COMPILER, AFFILIATION  DATE	<u> </u>	<del> </del>	- 12 - 12 - 12 - 12 - 12 - 12 - 12 - 12			
OTHER INFORMATION AS APPROPRIATE  SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)  Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.  COMPILER, AFFILIATION  DATE						
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.  COMPILER, AFFILIATION  DATE		,				
Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.  COMPILER, AFFILIATION  DATE	OTHER INFORMATION AS ALT NOT MA					
Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.  COMPILER, AFFILIATION  DATE						
Lyle, Royster, Jr. and Simpson, Pamela. The Architecture of Historic Lexington. 1977.  COMPILER, AFFILIATION  DATE	COLIDOR OF INFORMATION (IACA LICE	NG LISTING ON MA	TIONAL BECIETED C	TATE DECISE	EDC ETC!	
COMPILER, AFFILIATION DATE						
0.70.700						
0.70.700	COMPUED AFFILIATION				DATE	
	Druscilla J.Null, HABS				8/18/83	